

Leominster and Hampton Locality

Locality Steward:

Colin Smith

Upcoming Leave:
11-15 May 2026.

Covering the wards of:

Hampton
Leominster East
Leominster South
Leominster West

To Date Facts- Jan

Enquiries Raised to date for LS	156
Defects Raised in Locality	462
Emergency Defects Raised	21
Self Completed Jobs by LS	17

Self Completed Works

An Example of some of the works completed by myself this week.

Location: A4110 Stretford

Type of repair: Re-open gully



Example 1

Example 2



All defects on the network need to be reported through the correct channels

For General Enquiries:

Online (general non-emergency enquiries):

[Report problems on the road – Herefordshire Council](#)

[FixMyStreet](#)

[Home - report app \(herefordshire.gov.uk\)](#)

24/7 Phone number:

01432 261800

To Check progress on a defect:

[Pothole and road defect progress map – Herefordshire Council](#)

To view current and upcoming roadworks

<https://one.network/>



Locality Weekly Update

Storm Chandra brought yet more water to an already saturated landscape bringing flooding back to the usual areas but also, some new ones. Roads closed due to flooding have to be checked for safety by the LS team before they can be re-opened. Alongside a continuous barrage of Enquiries and the flooding issues this week I have finally completed the quarterly Leominster Accident Cluster Sites inspection.

Next Week

To Bromyard for the monthly 'B' roads inspection; then the Hampton and Leominster 'A/B' roads monthly; the Leominster Play areas if time.



Seasonal/Important Info

Reporting road issues – a plea

As a reminder (and except where community members are unable to ring in or raise online themselves) PLEASE encourage reporting directly by the person who has identified the problem themselves using one of the options in the orange box above. This helps speed up the report and to avoid duplication; gets the location exactly right or gives an option to speak to the 'witness' directly to confirm the site; aids the triage of the most serious network safety issues which can then be attended and resolved first. Many thanks!

HC roadside grit bins

Please report any HC roadside grit bins which need to be restocked.

Completed Defects this week by ward.
(Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Hampton	C1121 From Bodenham Manor To Millcroft Road	Spillway to gully blocked off with mud / debris. Scraped off by LS.	1
	Wacton Farm Lane, Bredenbury	Re-stock all HC grit bins	
	Pudleston Court Access Lane	Replace damaged grit bin and re-stock	1
	A44 Grendon Green crossroads	Install Flood boards	
	C1062 From A44 To Great Wacton Lane	Gully - Clean & Prove Connection	1
	Bowley Lane, Bodenham	Vegetation - Cut Back Hedges obscuring forward visibility of Back-to-back 40/NSL signs	50M
	A44 Steensbridge	Carriageway surface defect repairs	1
	A44 From Little Priddleton To Westington		1
	Grendon Green Lane, Bredenbury		3
	C1114 Bodenham Moor To Hollybush Cottage		4
Leominster East	A44 From A49 Roundabout To C1055	Flood boards installed and installed again by LS	Two separate events
	A44 From A49 Roundabout To C1055	Loose debris from failed surface patch removed from carriageway edge	
	St Botolphs Green	Vegetation - Cut Back Hedges	18M

Completed Jobs this week by ward.
(Completed between last Wednesday and 23:59hrs this Wednesday)

Ward	Location	Job Type	No. Completed
Leominster East	A44 From A49 Roundabout To C1055	Vegetation - Cut Back Hedges obscuring forward visibility of raised warning sign (ACS)	40M
	A44 From C1055 To Fairmile Bungalow	Carriageway surface defect repairs	2
	A44 From A49 Roundabout To C1055		1
Leominster South	A4110 From A44 To Stretford Road B4457	Gully lost in verge overgrowth. Scraped off by LS.	1
	Newtown Lane From C1105	Install Road Closed signage due to flooding	
	Ivington Road C1105	Install Road Closed signage due to flooding then replace with Flood Boards	
	A44 From C1085 To Moor Brook	Fly Tipping Collection in layby	Tyres dumped and general litter pick
	Brierley Lane	Fly Tipping Collection	Large lump of concrete within highway extent
	George Street	Street Sweeping – Detritus	200M
	Churchill Avenue	Street Sweeping – Detritus	600M
	A44 From C1085 Via Monkland To Moor Brook	Carriageway surface defect repairs	5
Leominster West	Monkland Road A44	Fly Tipping Collection	2 pieces of roofing sheet
	Cholstrey Road B4529	Carriageway surface defect repair	2